

STEVENS PASS SEWER DISTRICT
Monthly Meeting Agenda
July 16, 2026 at 10:00AM
34000 N Nason Rd, Leavenworth, WA
Conference Call Phone Number: (978) 990 5073
Meeting ID: 334 557 8#

Agenda

Commissioners: Stephanie Ogden, Casey Cass, Jeff Andreas

Public Comment Period:

1. Written or verbal comments

Consent Agenda:

1. Approve minutes from June 18, 2026 regular meeting.
2. Approve previously submitted vouchers:
 - Vouchers 9723 to 9725 \$23,566.38
 - Vouchers 9726 to 9728 \$26,197.01
 - Vouchers 9729 to 9732 \$2,470.53
 - Vouchers 9733 to 9736 \$40,213.94
 - D1392 to D1397 \$9,433.73
 - P2950 and P2951 \$6,390.72 pay period 6/1-6/15/26
 - P2952 to P2954 \$8,521.84 pay period 6/16-6/30/26
 - P2955 and P2957 \$590.17 June Commissioners
3. Related Party Transactions
 - Stevens Pass Mountain Resort monthly service fee is current.

Old Business:

1. Plant Report and Update.
2. Blower Project Update.
 - Project is underway.
 - Modulating valves to be tested on Thursday 7/16/2026.
 - 1 membrane blower, 1 aeration blower, and 1 set of diffusers to be tested beginning 7/21/2026.
3. New Permit.
 - Reply to factual review draft has been sent to Ecology.
 - Temperature reduction is being evaluated and strategized for near term.
 - Nitrate operational control will not be tested until blower project is complete.

STEVENS PASS SEWER DISTRICT
Monthly Meeting Agenda
July 16, 2026 at 10:00AM
34000 N Nason Rd, Leavenworth, WA
Conference Call Phone Number: (978) 990 5073
Meeting ID: 334 557 8#

New Business:

1. New Connection in Yodelin.
 - Existing cabin that had not been connected.
 - Leslie Llado cabin, formerly the Malloy (M2) cabin.

2. Stuck water plant backwash 7/6/2026 – 7/7/2026.
 - 16 - 20 hours of excessive 'slug' discharge. 45,000 extra gallons.
 - PFE alarmed at 10:30 pm.
 - Limited storage due to construction.
 - Required operator to be onsite due to temporary construction effluent bypass utilizing manual valves for discharge.
 - Flow lowered pH of Effluent.

3. Resort's Vehicle Shop Reconnection.
 - Vehicle shop was disconnected from collection system in 2016 due to oil/diesel discharge that severely damaged filters nearly allowing oil to enter creek. Plant had to stop operating for several months. Oil had to be monitored for 5 years, requiring weekly trips to testing lab in Everett. Filters had to be replaced twice, requiring upgrade due to obsolescence of modules. The first replacement was due to the initial contamination, the second was due to residual oil.
 - Resort wants to reconnect restroom and handwash sink. Oil/water separator and shop sink would remain disconnected.
 - Ecology had told District that the shop was never to be allowed to reconnect, but this conversation was not documented.